MASTER METALS. INC.. 2850 W. THIRD ST., CLEVELAND, OHIO 44113 • (216) 621-2361 FAX 621-7475

Lead Smelter and Refiner

17 June 1992



BECEIVED
JUL 2 4 1992

OFFICE OF RCRA
Waste Management Division
U.S. EPA, REGION V

United States Department of Justice Environmental Enforcement Section P.O. Box 7611
Ben Franklin Station
Washington, D.C.

U.S. Attorney for the Northern District of Ohio 1404 East Ninth Street Cleveland, Ohio 44114

Ohio Environmental Protection Agency Northeast District Office Division of Solid and Hazardous Waste 2110 East Aurora Road Twinsburg, Ohio 44087-1969

Section Chief
Ohio Environmental Protection Agency
Division of Solid and Hazardous Waste Management
1800 Watermark Drive
P.O. Box 1049
Columbus, Ohio 43265-1049

Branch Chief U.S. EPA, Region V RCRA Enforcement Branch, 5hr-12 230 South Dearborn Street Chicago, Il 60604

RE: Monthly Status Report 1 June 1992 to 30 June, 1992

In accordance with the reporting requirements of Section X.A. of the Consent Decree, the following is a description of the measures Master Metals has taken in the month of June and additional measures that will be taken to comply with the requirements of the Consent Decree.

Waste Characterization

To ensure reporesentative sampling of the slag Master Metals will institute the sampling procedure attached. In addition, two slag bins will be used. The permanently covered slag bin will be used to store sampled slag and subsequent slag produced until sample results are received. If the results indicate that the sampled slag is non-hazardous then all of the slag in the bin will be transferred to slag bin #3 to be stored until hauled to a sanitary landfill. If the results indicate that the sampled slag is hazardous the slag will be recycled in the rotary furnaces or taken to a hazardous waste facility for disposal.

Shift supervisors will be responsible that the atrea around the slag bins are kept clean to ensure that no lead containing materials are accidently mixed with the slag.

As of this time the permanently covered slag bin is being repaired. The floor is being reinforced so that slag molds can be flipped inside the bin.

Attached are the most recent slag results.

Financial Assurance

Master Metals currently has in excess of \$ 54,000 deposited in a Facility Closure Trust Fund. This is believed to be the amount that is required in accordance with Master Metals' current facility cost estimate.

Financial Insurance

Master Metals EIL insurance has been renewed with United Coastal Insurance Company.

Certification:

I certify that the information explained in or accompanying this document is true, accurate, and complete.

Very truly yours,

Douglas K. Mickey President